

N60200.AR.009166
NAS CECIL FIELD
5090.3a

SAMPLING AND ANALYSIS OUTLINE FOR BUILDING 606 NAS CECIL FIELD FL
3/1/1996
ABB ENVIRONMENTAL

**SAMPLING AND ANALYSIS OUTLINE
BUILDING 606
BASE REALIGNMENT AND CLOSURE
ZONE A, YELLOW WATER WEAPONS AREA
GROUP VII
NAVAL AIR STATION CECIL FIELD
JACKSONVILLE, FLORIDA**

Unit Identification No. N60200

Contract No. N62467-89-D-0317/090

Prepared by:

**ABB Environmental Services, Inc.
2590 Executive Center Circle, East
Tallahassee, Florida 32301**

Prepared for:

**Department of the Navy, Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
North Charleston, South Carolina 29419**

Steve Wilson, Code 18B9, BRAC Environmental Coordinator

March 1996

TABLE OF CONTENTS

Sampling and Analysis Outline
Building 606
Base Realignment and Closure
Zone A, Yellow Water Weapons Area, Group VII
Naval Air Station Cecil Field
Jacksonville, Florida

<u>Chapter</u>	<u>Title</u>	<u>Page No.</u>
1.0	SITE DESCRIPTION	1
2.0	ENVIRONMENTAL BASELINE SURVEY COLOR DESIGNATION	1
3.0	RECOMMENDATIONS	1
4.0	SELECTED REFERENCES	1

LIST OF FIGURES

<u>Figure</u>	<u>Title</u>	<u>Page No.</u>
1	Building 606 Enlisted Dining Hall	2

GLOSSARY

ABB-ES ABB Environmental Services, Inc.
EBS Environmental Baseline Survey
NAS Naval Air Station
PCB polychlorinated biphenyl
UST underground storage tank

1.0 SITE DESCRIPTION

This Base Realignment and Closure Phase II Sampling and Analysis Outline briefly describes and proposes a plan for assessment of Building 606 at Naval Air Station (NAS) Cecil Field. Building 606 is located on the south side of Main Road, between Guard House Post Number 1 and Yellow Water Weapons Compound (Figure 1). The facility is referred to as the Enlisted Dining Hall in the Environmental Baseline Survey (EBS) Report (ABB Environmental Services, Inc. [ABB-ES], 1994).

2.0 ENVIRONMENTAL BASELINE SURVEY COLOR DESIGNATION

Building 606 was color coded White in the EBS Report. However, a 3,000-gallon fuel oil underground storage tank (UST) is listed in the Tank Management Plan UST inventory. This was confirmed during an ABB-ES site reconnaissance walkover in August 1995. The UST is located approximately 30 feet northwest of the northwest corner of the building.

Four polychlorinated biphenyl (PCB)-contaminated pole-mounted transformers are located in the vicinity of Building 606. No visible indications of dielectric fluid leakage were noted during the EBS or subsequent site walkovers.

3.0 RECOMMENDATIONS

No Phase II sampling or analysis is recommended for this facility. Potential environmental concerns associated with the fuel oil UST will be addressed separately by the Tank Management Plan. Management of PCB-contaminated electrical equipment is being coordinated through the NAS Cecil Field Environmental Department. No other concerns were identified in the EBS Report or during subsequent site walkovers.


A recommendation to reclassify the color code for Building 606 is pending a satisfactory resolution of UST-related issues.

4.0 SELECTED REFERENCES

ABB Environmental Services, Inc. (ABB-ES), 1994a, Base Realignment and Closure Environmental Baseline Survey Report, Naval Air Station (NAS) Cecil Field, Jacksonville, Florida: prepared for Southern Division, Naval Facilities Engineering Command (SOUTHNAVFACENGCOM), November.

ABB-ES, 1994b, Project Operations Plan for Cecil Field and Health and Safety Plan: prepared for SOUTHNAVFACENGCOM, December.

ABB-ES, in press, Base Realignment and Closure Tank Management Plan for NAS Cecil Field, Jacksonville, Florida: prepared for SOUTHNAVFACENGCOM.



0 50 100
SCALE: 1 INCH = 100 FEET

FIGURE 1
BUILDING 606
ENLISTED DINING HALL



**GROUP VII SAMPLING AND
ANALYSIS OUTLINE**

**NAS CECIL FIELD
JACKSONVILLE, FLORIDA**

FACILITY 606