

N60201.AR.000451  
NS MAYPORT  
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
REVIEW OF MONITORING REPORT FOR ECHO PIER NS MAYPORT FL  
3/23/1999  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

580  
~~603~~

# Department of Environmental Protection



Lawton Chiles  
Governor

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

Virginia B. Wetherell  
Secretary

March 23, 1999

Ms. Beverly Washington  
Department of the Navy, Petroleum Program  
Southern Division - Naval Facilities Engineering Command  
PO Box 190010, 2155 Eagle Drive  
North Charleston, SC 29419-9010

*file: echo\_mol.doc*

RE: Monitoring Report - Echo Pier, Naval Station Mayport, Mayport, FL

Dear Ms. Washington:

I have reviewed the above document dated December 1998 (received January 11, 1999). The report noted the presence of free product in monitoring well MP-EP-02 and that the analytical results for benzene from that well following free product removal was below the upper limits specified in the MOP Order dated June 16, 1997. At the next sampling event, please conduct analyses for semivolatile petroleum constituents (EPA Method 610 or other appropriate methods as specified in Table I of Chapter 62-770, F.A.C.). After that, we should meet and determine how we should continue the monitoring at the site.

If you have any questions, please give me a call at 850-921-4230.

Sincerely,

James H. Cason, P.G.  
Remedial Project Manager

TJB\_\_\_\_\_ JJC\_\_\_\_\_ ESN\_\_\_\_\_