

N60201.AR.000765
NS MAYPORT
5090.3a

LETTER REGARDING THE TRANSMITTAL OF LIMITED CLOSURE SUMMARY REPORT
FOR BUILDING 1338 UNDERGROUND STORAGE TANK 1342 NS MAYPORT FL
12/2/2004
NAVAL STATION MAYPORT



DEPARTMENT OF THE NAVY

NAVAL STATION

MAYPORT, FLORIDA 32228-0112

IN REPLY REFER TO:

5090.15
5090.16
Ser N4E7/3464
December 2, 2004

Mr. Tom Griffin
Environmental Quality Division, ERMD
City of Jacksonville
117 West Duval Street, Suite 225
Jacksonville, Florida 32202

Dear Mr. Griffin:

SUBJECT: STORAGE TANK N1342 LIMITED CLOSURE SUMMARY REPORT,
NAVAL STATION MAYPORT, FDEP FACILITY ID 168626008

Naval Station (NAVSTA) Mayport submits the Limited Closure Summary Report and DEP Form 62-761.900(8) for the subject tank. A new sump was installed and tested tight on October 8, 2004. The piping leading from the separator to the sump failed tightness testing and the system will not be put back into operation until the double walled piping is replaced. All visibly contaminated soil was removed from the excavation and the required sampling results are included.

Please review this report to determine if this site requires additional site assessment activities or if it qualifies for a No Further Action determination.

If you have any questions, please contact NAVSTA Mayport, N4E7, Ms. Patricia Loop, at 904-270-6730 x212, FAX 904-270-7398, E-mail patricia.loop@navy.mil.

Sincerely,

CHERYL L. MITCHELL
Environmental Director
By direction of the
Commanding Officer

Enclosure (1)

Copy to:

Florida Department of Environmental Protection, Tallahassee (Jim Cason)

U.S. Environmental Protection Agency, Region IV (Craig Benedikt)
(w/o encl)

Commander, Navy Region Southeast (N46E) (w/o encl)

Naval Facilities Engineering Field Division South (ES31BW)

Tetra Tech NUS, Tallahassee (Terry Hansen)

Tetra Tech NUS, Jacksonville (Mark Peterson)