

N60201.AR.002894
NS MAYPORT
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
REVIEW AND COMMENTS ON TRANSFORMER SPILL AT BUILDING 1469 NS MAYPORT FL
02/20/2015
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



**FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION**

BOB MARTINEZ CENTER
2600 BLAIRSTONE ROAD
TALLAHASSEE, FLORIDA 32399-2400

RICK SCOTT
GOVERNOR

CARLOS LOPEZ-CANTERA
LT. GOVERNOR

JONATHAN P. STEVERSON
SECRETARY

February 20, 2015

Naval Station Mayport
Environmental Department
Attn: Mr. Paul Malewicki
P.O. Box 280067
Jacksonville, Florida 32228-0067

RE: Source Removal Report for Transformer Spill, Spill at Building 1469, Naval Station Mayport, Facility ID# 16-8626008, USEPA ID #FL9 170 024 260, Mayport, Florida (NAVFAC SE, December 17, 2014)

Dear Mr. Malewicki:

I have reviewed the subject document dated December 17, 2014. The document was received on January 13, 2015.

The following observations have been made pertaining to the Discharge Reporting Form.


1. The date of discovery of the confirmed discharge and the completion of this form was October 21, 2014.
2. The electrical transformer contained non-PCB mineral oil dielectric fluid.
3. The only media affected by the spill is soil.

Based on my review of the document, the Department concurs that the procedures and protocols outlined in the Department's revised Mineral Oil Dielectric Fluid Emergency Response Action Protocol, dated April 2007, have been followed. Based on these observations, Naval Facilities Command Southeast (NAVFAC SE) has met the requirements of Rule 62-780.560, Florida Administrative Code *Petroleum or Petroleum Product De Minimis Discharges*, and no further action is required.

Source Removal Report for Transformer Spill
Spill at Building 1469, Naval Station Mayport
Page 2
February 20, 2015

Thank you for the opportunity to review this document. If you require additional clarification or other assistance, please feel free to contact me at 850/245-8999.

Sincerely,

A handwritten signature in blue ink that reads "John Winters". The signature is written in a cursive style with a large initial "J".

John Winters, P.G.
Remedial Project Manager
DOD & Brownfields Partnerships Section

KAW 

cc Tim Bahr, FDEP, Tallahassee