

N60201.AR.002895
NS MAYPORT
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
REVIEW AND APPROVAL OF BIOX INJECTION LETTER REPORT FOR SITE 1586 NS
MAYPORT FL
02/20/2015
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



**FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION**

BOB MARTINEZ CENTER
2600 BLAIRSTONE ROAD
TALLAHASSEE, FLORIDA 32399-2400

RICK SCOTT
GOVERNOR

CARLOS LOPEZ-CANTERA
LT. GOVERNOR

JONATHAN P. STEVERSON
SECRETARY

February 20, 2015

Naval Facilities Engineering Command Southeast
Attn: Mr. Dana Hayworth OPUE3, Remedial Project Manager
135 Ajax Street North, Building 903
Naval Air Station Jacksonville
Jacksonville, Florida 32212-0030

RE: BIOX Injection Letter Report, Site 1586, Naval Station Mayport, Facility ID# 16-8626008, USEPA ID #FL9 170 024 260, Mayport, Florida (Tetra Tech, February 17, 2015)

Dear Mr. Hayworth:

I have reviewed the subject document dated February 17, 2015. I received this document on February 18, 2015. This document was completed under Contract Task Order Number JM33.

Based on my review of the document, the Department notes that the second BIOX[®] injection for Site 1586 was conducted from April 28 to May 2, 2014. The Department concurs with conducting quarterly groundwater monitoring at the site to determine the effectiveness of the 2014 BIOX[®] injections.

Thank you for the opportunity to review this document. If you require additional clarification or other assistance, please feel free to contact me at 850/245-8999.

Sincerely,

A handwritten signature in blue ink that reads "John Winters".

John Winters, P.G.
Remedial Project Manager
DoD and Brownfields Partnerships Section

KAW

Handwritten initials "KAW" in blue ink.

cc Bryan Baker, FDEP, Tallahassee

DOD_8_1287