

Department of Environmental Protection

32501.032
09.01.32.0048

Lawton Chiles
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Virginia G. Wetherell
Secretary

August 14, 1996

N00204.AR.001187
NAS PENSACOLA
5090.3a

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. Bill Hill
Code 1851
Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
P.O. Box 190010
North Charleston, South Carolina 29419-9010


RE: Final Remedial Investigation Report, Operable Unit 10 and
Site 13, NAS Pensacola

Dear Mr. Hill:

As my comments of November 14, 1996 have been addressed related to the technical review of the errata pages submitted November 8, 1995 (received November 9, 1995) for the above referenced document, the document is approved as final. Any remedial decision for this site will need to be re-evaluated depending on the results from the sediment and surface water analysis for Site 42 (Pensacola Bay). Also, the volatile contamination in monitoring well 33G15 will either need to be further delineated or the groundwater recovery and treatment system redesigned to capture the constituents. This can be specified in the modification to the RCRA permit.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,



John W. Mitchell
Remedial Project Manager


cc: Ron Joyner, NAS Pensacola
Jay Bassett, USEPA Region IV
Henry Beiro/Brian Caldwell, Ensafe, Pensacola
Karen Atchley, Bechtel, Knoxville
Tom Moody, FDEP Northwest District
Pat Kingcade, OGC/Trustee File

Mr. Bill Hill
August 14, 1996
Page two

Reviewed by:



Timothy J. Bahr; P.G.
Professional Geologist supervisor
Bureau of Waste Cleanup



8/14/96

Date

JJC WJC ESN ESN