

NAS PENSACOLA ECO MEETING SUMMARY

Date: October 21, 1996 Place: Pensacola Time: 1:00 - 4:30

Attendees: Bill Hill (Meeting Leader) Bill Gates (Facilitator/Notetaker)
John Mitchell (FDEP) Gena Townsend (EPA)
Denise Klimas (NOAA) Joan Dupont (EPA)
David Trimm (EnSafe)

	STATUS OF ACTION ITEMS FROM PREVIOUS MEETING	STATUS
9609-ED02	Wetland 6 sample locations 10 and 11 become part of Wetland 64 contingent on field confirmation by David.	Agenda
9609-ED03	Wetland W2 remains fresh water contingent on field confirmation by David.	Agenda
9609-EA01	Chuck to confirm wetland surface water sampling data available.	Agenda
9609-EA02	Chuck to compile individual PAHs and pesticides contamination results, TELs, and PELs for all wetlands including surface water data.	Agenda
9609-EA03	Chuck to resolve Wetlands 52 and 56 sampling locations A1.	Agenda
9609-EA04	Chuck to change TOC units to percent.	Agenda
9609-EA05	Chuck to further describe Wetland 79 because it has the potential to be eliminated as having a wetland determination.	Agenda
9609-EA06	Chuck to present above by Nov. 1	Agenda
9609-EA07	David to prepare volatiles only (detects) list for Sites 40 and 42 by October 11	Complete
9609-EA08	Chuck to review Wetland 64 data and propose transferring a portion of 64 to Site 40	Agenda

ACTIONS AND DECISIONS GENERATED FROM THIS MEETING

9610-EA09	David to contact Mike Lewis, EPA Gulf Breeze, to obtain his Site 40 sampling locations and analytical results	Agenda
9610-EA10	All Eco Team members provide comments to Team on David's Sites 40/42 proposal by November 1	Agenda

9610-ED08

The following table identifies sampling stations at Site 40 requiring further sampling.

Zone	Station	Color	HQ	Metals	PAHs	Pest/PCB
1	29	Red	31	@	a	
1	30	Red	26	@		
1	9	Orange	11.2	@		a-PCB
1	1,2,3	Blue				
2	18-24	Red	33	@	a	@-PCB
2	5-6	Orange	12	@	a	a-PCB
2	28	Orange				
3	4-8	Red	10-19		@	
3	13,15	Blue				
4	19	Red		@	@	
4	8	Orange		@	@	
4	13,14	Blue				

Notes:

a - contaminant present

@ - primary contaminant

Next Meeting

EPA, Atlanta Federal Center, 100 Alabama Street, Conference Rm. 9E

November 6, 1000 - 5:00

November 7, 8:00 - 5:00

Aaenda

Item	Goal	Time	Topic Leader
Check-In Processes Ground Rules		.5	Bill H.
Site 40			
Determine Site 40 Assessment/ Measurement Endpoints (9610-EA09, 10)	Resolution	2.0	David
Determine Assessment Zones Requiring No Further Action (9610- ED08)	Resolution	0.5	David
Prioritize Assessment Zones Requiring Further Study (9610-ED08)	Resolution	1.0	David
Limit the Number of Assessment Zones for Further Study (9610-ED08)	Resolution	1.0	David

Site 42			
Determine Site 42 Assessment/ Measurement Endpoints, etc	Resolution	2.0	David
Determine Assessment Zones Requiring No Further Action	Resolution	0.5	David
Prioritize Assessment Zones Requiring Further Study	Resolution	1.0	David
Limit the Number of Assessment Zones for Further Study	Resolution	1.0	David
Site 41			
Determine Assessment/Measure- ment Endpoints (9609-ED09/EA06)	Resolution	2.0	Chuck
9606-ED02,3	Resolution	.25	David
9606-EA01,2,3,4	Info Share	.25	Chuck
9609-EA05,8	Resolution	.25	Chuck
Prioritize Wetlands Requiring Further Study	Resolution	1.0	Chuck
Limit Wetlands Requiring Further Study by Grouping	Resolution	1.0	Chuck