



DEPARTMENT OF THE NAVY
SOUTHERN DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
P.O. BOX 190010
2155 EAGLE DRIVE
NORTH CHARLESTON, S.C. 29419-9010

32501.022
08.01.22.0001
N00204.AR.001234
NAS PENSACOLA
5090.3a

5090/13
Code 1851
14 Nov 96

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Ms. Gena Townsend, RPM
U. S. Environmental Protection Agency, Region IV
4WD/FFB
Atlanta Federal Center
100 Alabama Street, SW
Atlanta, GA 30303-3104

Subj: NAS PENSACOLA INSTALLATION RESTORATION PROGRAM SITE **22**,
REFUELER REPAIR **SHOP**

Dear **Ms.** Townsend:

This letter provides official notification that Site 22 has been transferred to the Petroleum Program. Fieldwork completed to date at the subject site has resulted in only petroleum related contaminants as indicated in the enclosed analytical results. This was addressed at the NAS Pensacola Tier I Partnering Meeting held in Charleston on 20 - 22 August 1996 and a decision was made to continue the investigation under the Petroleum Program. The site investigation will be completed under F.A.C. **62-770** and therefore will not be tracked in future Installation Restoration Site Management Plans. The site name has been changed to UST 26.

The following protocols were established during the October 22-23, 1996 Partnering Meeting:

a. Preparation of a separate Contamination Assessment Plan is not required since an existing Sampling and Analysis Plan under the CERCLA program has been approved and subsequent agreements concerning additional sampling have been agreed to by the NAS Pensacola Tier 1 team.


b. Investigation protocol should use Soil Cleanup Goals for Florida as the benchmark values for soil evaluation and remediation (as opposed to OVA soil headspace).

Subj: NAS PENSACOLA INSTALLATION RESTORATION PROGRAM SITE 22,
CRASH CREW TRAINING

c. Analytical protocol for groundwater should comply with the requirements set forth in F.A.C. 62-770.

If you have any questions, please call de or Bill Gates at (803) 820-7324 or (803)820-7360, respectively.

Sincerely,



WILLIAM J. HILL
Environmental Engineer
Installation Restoration I Branch

Encl:
(1) Form 1's

copy to: (w/o encl)

NAS Pensacola (Mr. Ron Joyner, Code 00500)

NAS Pensacola (Mr. Harry White, Code 00806)

→ EnSafe (Henry Beiro, Brian Caldwell, Allison Dennen)

AK