

Department of
Environmental Protection

32501.036
09.01.36.0031
N00204.AR.001244
NAS PENSACOLA
5090.3a

Lawton Chiles
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Virginia O. Wetherell
Secretary

November 25, 1996

CERTIFIED MAIL
RECEIPT REQUESTED

Mr. Bill Hill
Code 1851
Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
P.O. Box 190010
North Charleston, South Carolina 29419-9010

RE: Draft Preliminary *Site Characterization Report Site 36*, NAS
Pensacola


Dear Mr. Hill:

I have completed the technical review of the above referenced document dated August 9, 1996 (received August 15, 1996). I agree with the overall recommendation that no further investigation is needed for the eastern portion of the IWIP Sewer Line, and that no further remedial action is needed for this area. However, action is needed to restrict the use of the groundwater in this area.

Also, further assessment is needed at the southwest portion of the sewer line at temporary monitoring well 036GR42 where lead was detected at 266 $\mu\text{g/L}$. Aluminum and iron were also elevated in this well at 50 and 70 times the respective secondary drinking water standard. I recommend 4 additional monitoring wells be installed to adequately determine if there is a lead plume in this area of the sewer line. I suggest placing one well approximately 60 feet upgradient of 036GR42, a well in the previous location of 036GR42, one well east of and side gradient of 036GR42, and the fourth well approximately 50 feet downgradient of 036GR52. Analysis should be for metals only.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,



John W. Mitchell
Remedial Project Manager

Bill Hill
January 19, 1995
PSCR Site 36
Page two

cc: Ron Joyner, NAS Pensacola
Gena Townsend, USEPA Region IV
Henry Beiro/Brian Caldwell, EnSafe, Pensacola
Allison Dennen, EnSafe, Memphis
karen Atchley, Bechtel, Knoxville
Tom Moody, FDEP Northwest District
Pat Kingcade, OGC/Trustee File

TJB

B

JJC

JJC

ESN

ESN