

Department of Environmental Protection

32501.016
09.01.16.0008
N00204.AR.001319
NAS PENSACOLA
5090.3a

Lawton Chiles
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

MAR 27 1997

Virginia B. Wetherell
Secretary

March 14, 1997

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. Bill Hill
Code 1851
Southern Division
Naval Facilities Engineering Command
2155 Eagle Drive
P.O. Box 190010
North Charleston, South Carolina 29419-9010

RE: Final *Preliminary Site Characterization Report Site 16*, NAS
Pensacola


Dear Mr. Hill:

I have completed the technical review of the above referenced document dated January 17, 1997 (received January 21, 1997). Although I agree with the conclusion that no further action (NFA) is applicable at this site, the following comments need to be addressed for the final document.

1. Figure 4-1 (Soil Boring Locations) is missing from the document.
2. Please correct on page 5-1, "three site monitoring wells" to "eight site monitoring wells."

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,


John W. Mitchell
Remedial Project Manager

cc: Ron Joyner, NAS Pensacola
Gena Townsend, USEPA Region IV
Henry Beiro/Brian Caldwell, EnSafe, Pensacola
Allison Dennen, EnSafe, Memphis
Karen Atchley, Bechtel, Knoxville
Tom Moody, FDEP Northwest District
Pat Kingcade, OGC/Trustee File

TJB



JJC



ESN

