


N60508.AR.000320
NAS WHITING FIELD
5090.3a

PUBLIC NOTICE RESTORATION ADVISORY BOARD SITES 39 AND 40 PRESENTATION
NAS WHITING FIELD FL
9/23/2009
TETRA TECH NUS



NAS Whiting Field, Sites 39 and 40 Background and Current Status

9/23/2009


Introduction

- Site 40, Basewide Groundwater
- Groundwater underlying the entire base
- UST and IR Sites



Introduction (continued)


- Site 39, Clear Creek
- Downgradient of Site 40



Overall Status

- Remedial Investigation Reports are currently being written
- Site 40 - fourth quarter of 2002
- Site 39 - first quarter of 2003


Component One: Site 40 Background



- Established as a site in 1997
- Determine any risk to human health and the environment
- Focus on problem areas

Component Two: Site 39 Background

- Low-lying, Receiving Water
- Has Site 40/NAS Whiting Field Impacted Clear Creek?
- Creekbed and Floodplain



Component Two: Status



- Report Writing In Progress
- Isolated sheen
- Ecosystem Appears Intact and Thriving

Conclusions

- Sampling completed
- Keep people and the environment safe
- Natural Attenuation



Next Steps

- Site 40 Report - fourth quarter of 2002
- Site 39 Report - first quarter of 2003