



**DEPARTMENT OF THE NAVY**  
BASE REALIGNMENT AND CLOSURE  
PROGRAM MANAGEMENT OFFICE WEST  
1455 FRAZEE RD, SUITE 900  
SAN DIEGO, CA 92108-4310

5090  
Ser BPMOW.SA/0502  
April 26, 2007

Mr. Henry Wong  
California Department of Toxic Substances Control  
Office of Military Facilities  
700 Heinz Avenue, Suite 200  
Berkeley, CA 94710-2737

Dear Mr. Wong:

Subj: TRANSMITTAL OF THE DRAFT WORK PLAN PCB REMEDIATION –  
BASEWIDE TRANSFORMER VAULTS (INCLUDING BLDG. 1), NAVAL  
STATION TREASURE ISLAND, SAN FRANCISCO, CALIFORNIA

Enclosure (1) the Draft Work Plan PCB Remediation – Basewide Transformer Vaults (including Building 1), at Naval Station Treasure Island, San Francisco, California of April 26, 2007 is provided for your review and comments. Comments are requested by Friday, May 25, 2007.

Thank you for your continued support of this program. Should you have any questions or need additional information, please contact Mr. Scott Anderson, Project Manager at (619) 532-0938 or Mr. Charles Perry, Lead Project Manager, at (619) 532-0911.

Sincerely,

A handwritten signature in black ink, appearing to read "J. Sullivan", written over a large, stylized circular flourish.

JAMES B. SULLIVAN  
BRAC Environmental Coordinator  
By direction of the Director

Encl: (1) Draft Work Plan PCB Remediation – Basewide Transformer Vaults (including Building 1), Naval Station Treasure Island, San Francisco, California

5090  
Ser BPMOW.SA/0501  
April 27, 2007

**Distribution:**

Ms. Christine Katin, U.S. Environmental Protection Agency, Region IX  
Ms. Agnes Farres, California Regional Water Quality Control Board  
Ms. Mirian Saez, Treasure Island Development Authority  
Mr. Jack Sylvan, Mayor's Office of Base Reuse and Development (w/out enclosure)  
Ms. Jill Bensen, CH2M Hill  
Mr. Gary Foote, Geomatrix Consultants  
Ms. Marcie Rash, Tetra Tech EM Inc.  
Mr. Pete Bourgeois, Shaw Environmental & Infrastructure

**Community RAB Members:**

Mr. Nathan Brennan  
Ms. Dale Smith  
Mr. Douglas Ryan  
Ms. Alice Pilram  
Mr. Saul Bloom, ARC Ecology

5090  
Ser BPMOW.SA/0502  
April 26, 2007

Blind copy to:

D. Silva, Code: ENV Bldg 1, 3<sup>rd</sup> Floor (1 unbound original; 2 bound copies)

S. Anderson, BPMOW.SA (2 Copies)

C. Perry, BPMOW.CP

X Drive File

Read File

Serial File

Writer: S. Anderson, BPMOW.SA, 2-0938

Typist: B. Foster, BPMOW.BF, 2-0914, MD:\DRAFT PCB WP SAP  
TRANSMITTAL26APRIL07\25 APR 07



N60028\_001440  
TREASURE ISLAND  
SSIC NO. 5090.3

ENCLOSURE

DRAFT WORK PLAN  
PCB REMEDIATION – BASEWIDE TRANSFORMER VAULTS  
(INCLUDING BUILDING 1)

DATED 26 APRIL 2007

THIS RECORD IS ENTERED IN THE DATABASE AND FILED AS

RECORD NO. N60028\_001441