

N00174.AR.000991
NSWC INDIAN HEAD
5090.3a

LETTER OFFERING COMMENTS FROM THE FEDERAL FACILITIES DIVISION OF THE
MARYLAND DEPARTMENT OF THE ENVIRONMENT'S HAZARDOUS WASTE PROGRAM
ON DRAFT WORK PLAN REMEDIAL/ REMOVAL ACTION FOR SITE 42 AND SITE 17 DATED
APRIL 2005 NSWC INDIAN HEAD MD
8/30/2005
MARYLAND DEPARTMENT OF THE ENVIRONMENT



MARYLAND DEPARTMENT OF THE ENVIRONMENT

1800 Washington Boulevard • Baltimore MD 21230

410-537-3000 • 1-800-633-6101

Robert L. Ehrlich, Jr.
Governor

Kendl P. Philbrick
Secretary

Michael S. Steele
Lt. Governor

Jonas A. Jacobson
Deputy Secretary

August 30, 2005

Shawn Jorgensen
Naval District Washington, Indian Head
Code HN2SJ, Bldg. 289
101 Strauss Avenue
Indian Head, MD 20640-5035

RE: Draft Work Plan Remedial/Removal Action for Site 42 – Olsen Road Landfill and Site 17, Naval District Washington Indian Head, April 2005

Dear Mr. Jorgensen:

The Federal Facilities Division of the Maryland Department of the Environment's Hazardous Waste Program offers the following comments on the above referenced document.

- 1) Section 1.2.1, page 1-2, third paragraph, second sentence
This sentence states that the abbreviation for 1,1,1-trichlorethane is TCE. This is incorrect. The appropriate abbreviation for 1,1,1-trichlorethane is 1,1,1-TCA.

This comment also applies to the acronym list on page IV.

- 2) Section 4.0, page 4-1, first bulleted point
The first and third sentences within this bulleted point are awkwardly worded. Please reword these sentences to clarify their meaning.

If you have any questions, please contact me at (410) 537-3791.

Sincerely,

Curtis DeTore
Remedial Project Manager
Federal Facilities Division

CD:mh

cc: Mr. Dennis Orenshaw
Mr. Jeff Morris
Mr. Horacio Tablada
Mr. Harold L. Dye, Jr.

