



NAVFAC

Naval Facilities Engineering Command

A close-up photograph of a green leaf with a red and yellow insect resting on it. The background is blurred, showing more of the leafy plant.

Vieques Environmental Restoration Program

Underwater and Beach Sites Estado y Plan para los Sitios


Submarinos y Playas de Vieques



■ Itinerario para UXO 16.1 (Fuera de la Costa)

Investigation 2017 / Trabajo de


Remedial A Plan (2021)



Remedial Investigation Sampling and Analysis Plan (2018) / Plan de Muestreo y Análisis para la Investigación

Feasibility Study Report (2020) / Informe de Estudio

Proposed Plan (2021)





Wide Area Assessment Fieldwork (2016-2017) / Trabais

Remediation Sampling (2018) / DRA

Assessment (2016-2017) / Trabajo para la Evaluación

Sampling and Analysis (2019) / Plan de Muestreo Análisis para la Investigación



la Evaluación de Área Amplia.

gación
nienza


menza

para la Evaluación de Área Amplia (2018) para la Remediación (comienza en 2019)

UXO 16 Near-shore Munitions Timeline



Categorías Cerca de la Costa en UX





Near-shore Munitions Removal

Example of a near-shore munitions item.



For more information / Para más información:
[Visit our website](#) / Visite nuestra página

Visit our website / Visite nuestra página de internet
www.navfac.navy.mil/Vieques

www.navfac.navy.mil/vieques



Like us on / Dele Like a nuestra página
Facebook/ViequesRestoration