

N60200.AR.003774
NAS CECIL FIELD, FL
5090.3a

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION APPROVAL OF 2002
ANNUAL AND FIRST QUARTER 2003 OPERATIONS AND MAINTENANCE STATUS
REPORTS FOR NUTRIENT INJECTION SYSTEM AT BUILDING 9 NAS CECIL FIELD FL
12/3/2003
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

December 3, 2003
OFFICIAL CORRESPONDENCE

Commanding Officer
attn: Mr. Gabe Magwood, Code ES24
Southern Division
Naval Facilities Engineering Command
Post Office Box 190010
North Charleston, SC 29419-9010

Dear Mr. Magwood:

I have completed my review of the 2002 Annual Operations and Maintenance Status Report for the period January 1, 2002 – December 31, 2002 and the First Quarter 2003 Operations and Maintenance Status Report for the period of January 1, 2003 – March 31, 2003, for the Nutrient Injection System at Building 9, Former Tanks 9L1 and 9L2, Naval Air Station Cecil Field, both reports dated August 2003 (both reports received September 15, 2003), prepared and submitted by Terraine Environmental Services, Inc. Both reports adequately describe the operations of the remedial systems at this site during the time period covered. Please use a site map figure similar to the attached figure in future reports. The maps in the two reports showed the locations of the injection wells but did not identify which injection well was which.

This electronic message is being sent in lieu of regular mail. If you have any questions concerning this review, please contact me at (850)245-8997.

Sincerely,

David P. Grabka, P.G.
Remedial Project Manager
MS4535
Florida Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400
Direct: 850.245.8997
FAX: 850.245.8703
david.grabka@dep.state.fl.us