

N60200.AR.003856
NAS CECIL FIELD, FL
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
APPROVAL OF DRAFT SAMPLING AND ANALYSIS OUTLINE REPORT FOR EXCAVATED
SOIL PILE AT RUNWAYS 18R AND 18L NAS CECIL FIELD FL
3/24/2004
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

March 24, 2004

OFFICIAL CORRESPONDENCE

Commanding Officer
attn: Mr. Mark Davidson, Code ES33
Southern Division
Naval Facilities Engineering Command
Post Office Box 190010
North Charleston, SC 29419-9010

Dear Mr. Davidson:

I have completed my review of the Draft Sampling and Analysis Outline Report for Excavated Soil Pile – Runways 18R and 18L, Naval Air Station Cecil Field, dated October 2003 (received October 16, 2003), prepared and submitted by Tetra Tech NUS, Inc. This report documents an investigation into an excavated soil and debris pile that was created by a contractor working for the Jacksonville Airport Authority as they dug a utility trench between Runways 18R and 18L. The report documents the sampling and analysis of samples collected from the soil and debris pile. The Draft SAOR appears to be suitable for its intended use and may be finalized. This approval should not be construed to indicate that further wastes are no longer present between the runways, but that the wastes and soils removed thus far appear to be relatively innocuous and that their presence between two runways posed little risks to human health and the environment.

This electronic message is being sent in lieu of regular mail. If you have any questions concerning this review, please contact me at (850)245-8997.

Sincerely,

David P. Grabka, P.G.
Remedial Project Manager
MS4535
Florida Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400
Office: 850.245.8907
Direct: 850.245.8997
FAX: 850.245.8703
david.grabka@dep.state.fl.us