

N60200.AR.003980
NAS CECIL FIELD, FL
5090.3a

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION APPROVAL OF FIRST
QUARTER 2004 OPERATIONS AND MAINTENANCE STATUS REPORT FOR AIR
SPARGING/SOIL VAPOR EXTRACTION SYSTEM AT 103RD STREET NAS CECIL FIELD FL
9/30/2004
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

September 30, 2004
OFFICIAL CORRESPONDENCE

Commanding Officer
attn: Mr. Nick Ugolini, Code ES42
Southern Division
Naval Facilities Engineering Command
Post Office Box 190010
North Charleston, SC 29419-9010

Dear Mr. Ugolini:

I have completed my review of the First Quarter 2004 Operations and Maintenance Status Report for the period of January 1, 2004 – March 31, 2004, for the Air Sparging and Soil Vapor Extraction System, 103rd Street and "A" Avenue, Naval Air Station Cecil Field, dated June 2004 (received June 10, 2004), prepared and submitted by Terraine Environmental Services, Inc. The report is suitable for its intent. I agree that post-active remediation monitoring should continue.

This electronic message is being sent in lieu of regular mail. If you have any questions concerning this review, please contact me at (850)245-8997.

Sincerely,

David P. Grabka, P.G.
Remedial Project Manager
MS4535
Florida Department of Environmental Protection
2600 Blair Stone Road
Tallahassee, FL 32399-2400
Direct: 850.245.8997
FAX: 850.245.8703
david.grabka@dep.state.fl.us