

N60200.AR.005217  
NAS CECIL FIELD, FL  
5090.3a

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION REVIEW OF THIRD  
QUARTER 2008 AND 2008 ANNUAL LONG TERM MONITORING AND OPERATION AND  
MAINTENANCE STATUS REPORTS FOR BUILDING 46 NAS CECIL FIELD FL

5/7/2009

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



# Florida Department of Environmental Protection

Bob Martinez Center  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

Charlie Crist  
Governor

Jeff Kottkamp  
Lt. Governor

Michael W. Sole  
Secretary

May 7, 2009

BRAC PMOSE  
Attn: Mr. Art Sanford  
4130 Faber Place Drive  
Suite 202  
North Charleston, SC 29405

RE: Third Quarter 2008 and 2008 Annual Long-Term Monitoring Operation and Maintenance Status Reports, Building 46, Former Naval Air Station Cecil Field, Jacksonville, Florida.

Dear Mr. Sanford:

I have completed my review of the Third Quarter 2008 and 2008 Annual Long-Term Monitoring Operation and Maintenance Status Reports, Building 46, Former Naval Air Station Cecil Field, dated December 22, 2008 and April 15, 2009, respectively (received January 6, 2009 and April 17, 2009, respectively), prepared and submitted by Solutions - IES, Inc. The reports are adequate for their intent. However, please correct an error on Figure 5 regarding the sulfate concentration detected in monitoring well CEF-046-06D in December 2008. The sulfate concentration plotted on the figure for that well should be 10,200 mg/L.

If you have any concerns regarding this letter, please contact me at (850) 245-8997.

Sincerely,

David P. Grabka, P.G.  
Remedial Project Manager

CC: Mark Speranza, TtNUS, Pittsburgh  
Mike Halil, CH2M Hill, Jacksonville  
Mike Fitzsimmons, FDEP, Northeast District  
John Flowe, City of Jacksonville  
Jessica Dehart, Solutions - IES, Raleigh, North Carolina

JJC *for* ESN *for*