

N60200.AR.003294  
NAS CECIL FIELD, FL  
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
COMMENTS ON ANNUAL GROUNDWATER MONITORING REPORT YEAR 3 FOR  
BUILDING 199 TANK 199 NAS CECIL FIELD FL  
4/5/2002  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

April 5, 2002  
OFFICIAL CORRESPONDENCE

Commanding Officer  
attn: Mr. Wayne Hansel, Code ES245  
Southern Division  
Naval Facilities Engineering Command  
Post Office Box 190010  
North Charleston, SC 29419-9010

Dear Mr. Hansel:

I have completed my review of the Annual Groundwater Monitoring Report, Year 3 (January 2002), Building 199, Tank 199, Naval Air Station Cecil Field, dated February 22, 2002 (received February 25, 2002), prepared and submitted by Tetra Tech NUS, Inc. While the report adequately documents the groundwater monitoring at the site, I do not concur with the recommendations to remove perimeter well MW-4S and removing VOCs, TRPH and PAHs from the analyte list for the perimeter wells. Sampling and analyses should continue as specified in the Department's May 10, 1999 Monitoring Only Plan Approval Order, the Department's August 29, 2000 letter accepting a reduced sampling frequency and other modifications previously agreed upon.

This electronic message is being sent in lieu of regular mail. If you have any questions concerning this review, please contact me at (850)921-9991.

Sincerely,

David P. Grabka, P.G.  
Remedial Project Manager  
MS4535  
Florida Department of Environmental Protection  
2600 Blair Stone Road  
Tallahassee, FL 32399-2400  
Office: 850.488.3935  
Direct: 850.921.9991  
FAX: 850.922.4939  
david.grabka@dep.state.fl.us