

N61165.AR.005018
CNC CHARLESTON
5090.3a

CLOSURE ASSESSMENT REPORT BUILDING 236 CNC CHARLESTON SC
02/15/1996
NAVFAC SOUTHERN

5090/14
Code 1844
15 Feb 96

Manager, Regulatory Section
South Carolina Department of
Health and Environmental Control
2600 Bull Street
Columbia, SC 29201

**CLOSURE ASSESSMENT REPORT, BUILDING 236, CHARLESTON NAVAL
SHIPYARD, CHARLESTON, SC, GWPD # N-10-GF-16459**

Enclosed are two copies of the Closure Assessment Report for the subject site prepared under subcontract by our remedial action contractor. This office apologizes for the lateness of this submission. Delays in report preparation were incurred by all contractors involved including the analytical contractor. It is our procurement policy now not to use our remediation contractor for tank removals thus reducing the number of subcontractor levels involved in producing the report. The submission of these reports is intended to meet the requirements for permanent closure specified by R.61-92.

If you have any questions or comments, please contact me at (803)743-0542.

Sincerely,

G. A. HUTTO
Environmental Engineer
Petroleum Remediation Division

Encl:

(1) UST Closure Report for Building 236, CNSY, Charleston, SC (2 copies)

ENVIR
18 circ
1844
Daily
J:\CORR\1844\DHEC2-15.DOC

1844x *BA*
~~1844~~
1844 *BA*