

N61165.AR.005037
CNC CHARLESTON
5090.3a

SOUTH CAROLINA DEPARTMENT OF HEALTH AND ENVIRONMENTAL CONTROL
ENVIRONMENTAL QUALITY CONTROL INSPECTION REPORT FOR DFSP HANAHAH CNC
CHARLESTON SC
01/13/1992
NAVFAC SOUTHERN

5090/11
Code 18231

13 JAN 1992

From: Southern Division, Naval Facilities Engineering Command
(Code 1823)

To: Defense Logistics Agency, DFSC - FQ, Cameron Station,
Alexandria, VA (Mr. Wayne Barnum)

Subj: **DFSP CHARLESTON, HANAHAN, SC - REMEDIATION PROJECT**

Encl: (1) South Carolina Department of Health and Environmental
Control (SCDHEC) Environmental Quality Control Inspec-
tion Report for DFSP Hanahan dated 9 Jan 92

1. The final inspection by SCDHEC of the remediation system at
DFSP Charleston, Hanahan, SC was completed on 9 Jan 92. Enclosure
(1) is a copy of the SCDHEC inspector's report submitted after the
inspection.

2. All of the items requiring action noted in enclosure (1) are
being addressed. There were no major deficiencies noted by SCDHEC
during the inspection. The requested information in enclosure (1)
will be forwarded to SCDHEC as soon as it is completed. All
indications from the SCDHEC inspector is that permission to operate
the entire remediation system will be issued the week of 13 Jan 92.

3. If you have any questions, please contact Mr. Daryle Fontenot,
Code 18231, at AUTOVON 563-0607.

H. J. FRASER
BY DIRECTION

182
09B
18231
Daily

1823
18231X

Source (Project): DFSP

Location: Hanahan

Mailing Address: _____

Owner/Operator: _____

County: BERKELEY

Person Contacted: _____
Date/Time Inspection: 1-9-92

Reason for Inspection/Investigation: FINAL INSPECTION
PERMIT # 15,707

Comments on Observations: ALL construction appears OK
Nutrient Facility - Completed except AS noted below
DEEP WELL - Chemical Results of water coming soon
Extraction Wells - AS - Come coming
Infiltration Gallery 243 - To be put into operation
N. Charleston Sewer District Requirements
O+M MANUAL Revised - Received
Updated AS-built - Received

1. Need chemical results of deep well water
2. Need backflow prevention test results

Permanent Tags on Valves in Infiltration gallery valve post

Recommendations/Follow-Action: Permanent tags on chemical feed pumps
specifying type of chemical feed and ~~number~~ infiltration gallery
Number pumped to.

Air Quality Only: _____
PGM ACT RC _____

Inspector: _____

OS NO. _____

Address: _____

SOURCE TYPE - SIP _____ NSPS _____ NESHAP _____ PSD _____
(mark ALL applicable)

Phone: _____

Signature Harvey Wilkins

DFSP FINAL INSPECTION 9 JAN 92

Harvey Wilkins

Daniel Thornley

~~Wayne Fanning~~

Herb Fraser

Don Matthews

Daryl Fontenot

Larry Verhasky

Rob Devlin

Don Vidalesky

Fred Robertson

~~Melinda Lewis~~

Ask about P.E. Test certification

Wayne Fanning - community letter

SCDHFC

Ask flow preventer test results wants

* Tag lines at valve box.

* nitrate level in deepwell no result get

* labeled nutrient locally pumps

Pump 12 running all the time.

TO DO NOT BORROW

Give SCDHFC O&M manual + BMP w/1 as built

* Results on deep well required from Grand Engineering.

SCDHFC TO
Look ~~over~~ O&M ^{manual} for issue permit to operate

[issue permit to operate all 3 operate at own discretion descriptions]

SCDHFC

Quarterly sampling results to SCDHEC Columbia 3 months after start
of system