

1813
181
GEC

DEPARTMENT OF HEALTH SERVICES

2151 BERKELEY WAY
BERKELEY, CA 94704

N00236.000403
ALAMEDA POINT
SSIC NO. 5090.3



November 27, 1989

Ms. Bella Dizon
Western Division
Facilities Engineering
900 Commodor Drive
San Bruno, CA 94066

Dear Ms. Dizon:

REVIEW OF THE MONITORING PLAN AIR QUALITY SWAT, NAS ALAMEDA

The Department has reviewed the above referenced plan and specific comments on the report are attached. Please ensure that results from this Solid Waste Assessment Test are integrated into the Remedial Investigation Program.

If you have any questions, please contact me at (415) 540-2122.

Sincerely,

Mark Malinowski
Engineering Geologist
Region 2
Toxic Substances Control Program

ENCLOSURE

cc: Mr. Randy Cate, Project Officer
Naval Air Station (Code OLE)
Alameda, CA 94501-5000

Julie Anderson, EPA
H. Brinkley, BAAQMD

CK:MM:tc-19

NOV 28 P1:44 '89

RECEIVED
IN CODE 181

403

COMMENTS ON THE
MONITORING PLAN AIR QUALITY SOLID WASTE ASSESSMENT TEST
ALAMEDA NAVAL AIR STATION

Pg	Sec	Pgph	Comment
8	3.3	1	Discuss how the holes left by the driven probes will be filled in. The Department recommends filling the holes with small chip or powdered bentonite. Do not use glazed tablets or pellets.
Appendix		B	Present information on well/boring 11 screen length.