

M600

MCAS EL TORO

4/17/89 TDP ~~FTE~~

ADDITIONAL SITES NEEDING INVESTIGATION

Tom D Peltier

Test Cells 658 and 447

Bldg. 626	Wash Rack
Bldg. 392	Wash Rack and Drum Storage Area
Bldg. 127	Wash Rack
Bldg. 673	Wash Rack and Drum Storage
Bldg. 390	Wash Rack
Bldg. 386	Steam Cleaning Area
Bldg. 298	Maintenance Shop
Bldg. 388	Wash Rack
Hanger 605	Aircraft Wash Area
Hanger 606	Aircraft Wash Area
Hanger 114	Aircraft Wash Area
Hanger 463	Aircraft Wash Area
Hanger 461	Aircraft Wash Area
Hanger 297	Aircraft Wash Area and Drum Storage
Bldg. 320	Trichloroethylene Drum Storage
Bldg. 357	Drum Storage
Bldg. 454/456	Drum Storage
Bldg. 317	Drum Storage
Bldg. 534	Drum Storage
Bldg. 655	Drum Storage
Bldg. 359	Drum Storage
Bldg. 130	Drum Storage
Bldg. 602	Drum Storage
Salvage Yard	Drum Storage

TITLE: ADDITIONAL SITES NEEDING INVESTIGATION. POTENTIAL AREAS OF CONTAMINATION

AUTHOR: TOM D. PELTIER/?

DATE: 4/17/89

CATEGORY: 1.2

OTHER POTENTIAL AREAS OF CONTAMINATION

Mag. 13	Paint Sheds
Auto Hobby Shop	Leaking waste Oil Tank
Bldg. 103	Paint Shed
Heavy Equipment	Vehicle Wash Area
Empty or Destroyed Buildings 143, 343, and 1789	
Combat Ready Vehicle Storage and Wash Area	
Bldgs. 359 & 651	Wash Areas
Bldg. 262	Wash Rack
Exchange Car Wash	