Proposed Remedial Action UXO 18, Cayo La Chiva Former Vieques Naval Training Range Vieques, Puerto Rico

the reason of the state of

Atlantic Fleet Weapons Training Area - Vieques Public Meeting August 2, 2016

Meeting Outline

Site Information

- Site Features, Planned Use, and Historical Use
- Environmental Investigations and Related Activities
- Investigation Findings
- Evaluation of Cleanup Options
- Proposed Cleanup (Remedial Action)
- Questions and Comments

UXO 18 (Cayo La Chiva) Location



Caribbean Sea

Playa La Chiva (Blue Beach)

Bahia de la Chiva

Punta Galintez

ECA – Eastern Conservation Area EMA - Eastern Maneuver Area LIA – Live Impact Area SIA – Surface Impact Area NASD - Naval Ammunition Support Detachment VNTR - Viegues Naval Training Range





Bahla de la Chiva **Punta Conejo**

Cayo La Chiva Features



Cayo La Chiva is 12 acres, located several hundred yards offshore of Playa La Chiva (Blue Beach)

Island is rocky,
 densely vegetated,
 and has steep cliffs
 on most sides

 Access to the island is limited to northern tip of island where a narrow sandy beach is present

Cayo La Chiva Planned Use

- Owned by the Commonwealth of Puerto Rico
- To be managed as a recreational area by Puerto Rico Department of Natural and Environmental Resources (PRDNER)
- Planned features include:
 - Beach use
 - Picnic areas
 - Interpretive trail
 - Observation tower

Land Use Plan



Anchorage Area

-Landing/Picnic Area

Trail Through Island-

Tourist Tree

Overlook/Picnic, Area



Historical Use



• Limited military training activity

- Records indicate a 0.50-caliber machine gun was located on the island that fired blank rounds during amphibious landings at Playa La Chiva
- Field observations identified five 5-inch rockets and three smoke canisters

Environmental Investigations/Related Activities

• Site Reconnaissance (2011)

- Inspection within accessible areas
- Five 5-inch rockets and three smoke canisters identified and removed
- Biological Assessment (2011)
 - No federally listed threatened or endangered plant or animal species were observed on island

• Archaeological Survey (2013)

- A reconnaissance was performed to identify potential cultural resources
- Remedial Investigation (2013)
 - Soil sampling across the site and at locations where munitions and munitions-related debris were found
 - Assessed the potential explosive hazards and potential human health and ecological risks





American kestrel

Site Inspections

5-inch Rocket

Smoke Grenade

Inspection Transect

Safety Measures Implemented

Warning Buoy and Sign Installation (2012)

- 7 warning signs installed on Cayo La Chiva
- 6 warning buoys installed around Cayo La Chiva
- 20 warning signs installed at Playa La Chiva, Punta Galintez, and Punta Conejo





Investigation Findings

- No known munitions present since the accessible areas were searched and munitions removed
- Because of historical military use, the potential presence of additional munitions must be assumed
 - Therefore, potential explosive hazards must also be assumed
- No environmental contamination related to historical military use
 - Therefore, no human health or ecological risk

Evaluation of Cleanup Options

• Basis for Cleanup (Remedial Action)

- Address potential explosive hazards to ensure Cayo La Chiva can be used for the planned recreational activities
- Remedial Action Objectives
 - Reduce any explosive hazard that may be present associated with potential munitions to be compatible with current and anticipated future land use
 - Reduce the potential for unauthorized access

Summary of Remedial Alternatives Evaluated

- Alternative 1 No action
- Alternative 2 Land Use Controls and Inspections
 - Warning signs and routine inspections to look for (and remove, if found) any munitions in areas being accessed
- Alternative 3 Focused Munitions Removal, Land Use Controls, and Inspections
 - Munitions clearance in areas identified for recreational use
 - Land Use Controls and inspections similar to Alternative 2
- Alternative 4 Island-wide Munitions Removal, Land Use Controls, and Inspections
 - Complete vegetation and munitions clearance across island
 - Land Use Controls and inspections similar to Alternative 2

Proposed Cleanup (Remedial Action)

- Alternative 3 Focused Munitions Removal, Land Use Controls, and Inspections
- Why Alternative 3 is the preferred cleanup:
 - Vegetation and munitions clearance is focused in areas identified by PRDNER for recreational use
 - Island-wide vegetation and ecological habitat are preserved
 - Land Use Controls and routine inspections will continue to ensure reduced explosive hazard
- Navy, EPA, PREQB, and PRDNER agree on the proposed cleanup alternative

Proposed Cleanup – Alternative 3



For More Information

Administrative Record File

- Biblioteca Electrónica
- http://www.navfac.navy.mil/vieques
- Navy Remedial Project Manager
 - Kevin Cloe

Navy On-Island Site Manager

- Madeline Rivera

• EPA Remedial Project Manager

Julio Vázquez

PREQB President

Weldin Ortíz

• **PRDNER Director of Marine Resources Division**

Craig Lilyestrom

What Next?

- Ask questions or provide comments during the Public Meeting or Public Comment Period
 - Talk to representatives of the Navy, EPA, PREQB, or PRDNER
 - If you want your comments or questions to be part of the official record:
 - Let us know so we can ensure the court reporter records your comment during the Public Meeting
 - Write your comment or question on the comment sheet and hand it to one of the representatives or mail it to one of the representatives listed in the Proposed Plan

Public comment period ends on August 25, 2016