

WATERFRONT WORK WITH BARGE CRANES MAKES FOR A CONGESTED WORK AREA



SNOW AND ICE NOT CLEARED OFF BARGE BEFORE GOING MOVING CRANE



CRANE BEING LIFTED FROM RIVER BOTTOM



CRANE BEING LIFTED FROM RIVER BOTTOM



0220 HOURS IN THE MORNING AND STILL WORKING
ON TRYING TO RECOVER THE CRANE



CRANE FINALLY RAISED FROM RIVER BOTTOM



RECOVERED SECTION OF THE BOOM



DAMAGED CRANE SITTING ON BARGE AFTER RECOVERY



VIEW OF OPPOSITE SIT OF CRANE



CRANE WAS A TOTAL LOSS



VIEW AFTER CRANE TAKEN TO CONTRACTORS YARD



LAST PIECE RAISED FROM BOTTOM WAS A CAB DOOR.

COST TO CONTRACTOR TO REPLACE CRANE WAS AT LEAST

\$\$\$\$\$\$\$\$\$\$\$\$ 1 MILLION DOLLARS \$\$\$\$\$\$\$\$\$\$\$\$\$

