

02.01-10/31/94-00210

(804) 322-4776

5090

1822:JFH:cag

OCT 31 1994

Virginia Department of Environmental Quality
Water Division
Attn: Ms. Amy Webster
287 Pembroke Office Park
Pembroke 2 Building, Suite 310
Virginia Beach, Virginia 23462

Re: Soil Removal Action at NALF Fentress

Dear Ms. Webster:

Attached are the Maps and laboratory data for the TPH removal Action at NALF Fentress. Floor sample number 6 (F6) represents an isolated area with elevated TPH content. Please note that the surrounding sample positions (F3, F5, F7, and F8) are either clean or very low. These positions are illustrated on Figure 1.

The other area with elevated readings is in the vicinity of the trailer represented by sample numbers F4, W8, and W9 also presented on Figure 1. Figure 4-1 (2nd Figure) shows old abandoned tanker trucks in this area. The runway in this area is very cracked and spalled. The complete data results and the corresponding numbering scheme are submitted as enclosure (2), Laboratory Certificate of Analysis.

Based on our phone conversation of October 7, 1994, the Navy has proceeded to backfill with bioremediated soil in this area. We would appreciate, in writing, a concurrence letter for our file on this subject by November 21, 1994. Please call at (804) 322-4776 if you have questions or need additional information with regards to this submittal.

Sincerely,

J. F. HARRIS, P.E.
Remedial Project Manager
Installation Restoration Section
(North)
Environmental Programs Branch
Environmental Quality Division
By direction of the Commander

Enclosure

Copy to:
VDEQ Richmond (Ms. Erica Dameron)
ROICC Oceana (Brian Moore)
NAS Oceana (Mr. Will Bullard)

Blind copy to:
1822 (JFH)
18S
vawbfen1.jfh