



DEPARTMENT OF THE NAVY

NORTHERN DIVISION  
NAVAL FACILITIES ENGINEERING COMMAND  
BUILDING 77L, U.S. NAVAL BASE  
PHILADELPHIA, PENNSYLVANIA 19112-5094

N00101 AR.000015  
NAS SOUTH WEYMOUTH  
5090.3a

IN REPLY REFER TO

5090  
Ser 1313/1423 (LM)

19 JUN 1991

*Jul*

Mr. Steve Johnson  
Massachusetts DEP  
Site Assessment Branch  
5 Commonwealth Avenue  
Woburn, MA 01801

Dear Mr. Johnson,

This letter is to confirm a telephone conversation with Mr. John Buckley of July 10, 1991 in which the Navy requested authorization to redeposit drill cuttings and well purge water back on to the original sites under investigation at Naval Air Station, South Weymouth (Massachusetts Identification Number 3-2621). The drill cuttings and purge water were drummed during the Site Investigation (SI) field work performed at the Naval Air Station, South Weymouth, MA in February 1991.

Soil, sediment and water samples were collected and analyzed using EPA's Contract Laboratory Procedures (CLP) for the full Target Compound List (TCL) and Target Analyte List (TAL). Results of the analysis performed on the soil, sediment and water samples are enclosed in Appendix H of the SI Report which was received in June 1991. Because of the low levels of contaminants found in the samples, we plan to redeposit the drill cuttings and purge water back on to the sites under investigation. The emptied drums will be disposed of in accordance with local, state and federal regulations. We will then proceed with the Remedial Investigation (RI) and remediate the sites under investigation, if necessary.

We will continue to keep you informed of our progress at the Naval Air Station South Weymouth. If you have any questions regarding this matter, please contact Ms. Lisa Nang-Marino at (215) 897-6280.

Sincerely,

*James M. LaBuen*

*for* A.E. Haring  
Head, Restoration Management Section

Encl: Draft Site Investigation Report for NAS South Weymouth