

N60200.AR.003222  
NAS CECIL FIELD, FL  
5090.3a

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION APPROVAL OF THIRD  
QUARTER 2001 OPERATIONS AND MAINTENANCE STATUS REPORT FOR NUTRIENT  
INJECTION SYSTEM AT BUILDING 9 FORMER TANKS 9L1/9L2 NAS CECIL FIELD FL  
2/14/2002  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

February 14, 2002  
OFFICIAL CORRESPONDENCE

Commanding Officer  
attn: Mr. Wayne Hansel, Code ES245  
Southern Division  
Naval Facilities Engineering Command  
Post Office Box 190010  
North Charleston, SC 29419-9010

Dear Mr. Hansel,

I have reviewed the Operations and Maintenance Status Report, 3rd Quarter 2001, Nutrient Injection System, Building 9, Former Tanks 9L1 and 9L2, Naval Air Station Cecil Field, dated November 2001 (received November 26, 2001), prepared and submitted by CH2M Hill Constructors, Inc. The report is adequate for its intent. I concur with the consultant's recommendation to continue operating the system as well as diverting 100 percent of the airflow into injection well CEF-9-14 in an attempt to increase the radius of influence around that well so it encompasses monitoring well CEF-9-9S.

This electronic message is being sent in lieu of regular mail. If you have any questions concerning this review, please contact me at (850)921-9991.

Sincerely,

David P. Grabka, P.G.  
Remedial Project Manager  
MS4535  
Florida Department of Environmental Protection  
2600 Blair Stone Road  
Tallahassee, FL 32399-2400  
Office: 850.488.3935  
Direct: 850.921.9991  
FAX: 850.922.4939  
david.grabka@dep.state.fl.us