

N61165.AR.005259
CNC CHARLESTON
5090.3a

NO FURTHER ACTION (NFA) UNDERGROUND STORAGE TANK (UST) ASSESSMENT
REPORT DATED 29 JULY 1998 FOR QUARTERS FF HOUSING CNC CHARLESTON SC
09/02/1998
SOUTH CAROLINA DEPARTMENT OF HEALTH AND ENVIRONMENTAL CONTROL



**SOUTHERN DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
FACSIMILE**



From The Desk Of

GABRIEL L. MAGWOOD

Facsimile No.: (843) 820-7465

Telephone No.: (843) 820-7307

THIS FACSIMILE CONTAINS FIVE (5) PAGES
April 24, 2001

To: **MICHAEL BISHOP
SCDHEC**

Facsimile No.: **(803) 898-3795**

Telephone No.: **(803) 898-3553**

NOTE:

I have attached two maps from the UST Closure Assessment.



2 September 1998

2600 Bull Street
Columbia, SC 29201-1708

COMMISSIONER:
Douglas E. Bryant

**Department of the Navy
 Southern Division NFEC
 P.O. Box 190010
 North Charleston, SC 29419-9010
 Attn: Mr. Gabriel Magwood**

BOARD:
John H. Burtriss
Chairman

William M. Hull, Jr., MD
Vice Chairman

Roger Leaks, Jr.
Secretary

Mark B. Kent

Cyndi C. Mosteller

Brian K. Smith

Rodney L. Grandy

**Re: Underground Storage Tank Assessment Report dated 29 July 1998
 Quarters "FF" Housing (Site Identification # 15405-General File)
 Charleston Naval Complex/Charleston Naval Base
 Charleston, SC
 Charleston County**

Dear Mr. Magwood:

The author has completed technical review of the referenced document. As submitted, the report provides a narrative describing closure activities and analytical results of environmental sampling conducted to determine if releases have occurred as a result of operation of the referenced vessel and/or associated piping system. The analytical results provided indicate that concentrations of BTEX and PAH compounds were not detected above established method detection limits in soil grab samples obtained from the UST excavation and/or piping run excavations. In this regard, the employed closure activities and sampling results appear to indicate that no additional endeavors for remedial actions and/or contaminant characterization are warranted for Quarters "FF" at this time.

With consideration to the above comments, the Department has reviewed the referenced environmental data. Based on the information and analytical data submitted, the Department recognizes that the Department of the Navy and Charleston Naval Complex/Charleston Naval Base has adequately addressed the known environmental contamination identified on the property to date in accordance with the approved scope of work. Please note, this statement pertains only to the portion of the site addressed in the referenced report and does not apply to other areas of the site and/or any other potential regulatory violations. Further, the Department retains the right to request further investigation if deemed necessary.

Charleston Naval Complex/Charleston Naval Base
2 September 1998
page 2


Should you have any questions please contact me at (803) 734-5328.

Sincerely,

Paul L. Bristol, Hydrogeologist
Groundwater Quality Section
Bureau of Water


Tom Knight, Manager
Groundwater Quality Section
Bureau of Water


cc: Trident District EQC




SPORTENVDECHASN
 1869 North Hobson Ave.
 North Charleston, SC 29405-2108
 Ph. (803) 743-8777

Site Map 2
 UST "FF"
 Charleston Naval Base
 Charleston, SC

DWG DATE: 11 JUN 98 | DWG NAME: UST FF_2



FORMER
UST QUARTERS FF



GRAPHIC SCALE

SPORTENVDETHASN
1899 North Hobson Ave.
North Charleston, SC
29405-2106
Ph. (803) 743-6777

Site Map 1
UST Quarters FF
Charleston Naval Base
Charleston, SC

DWG DATE: 29 MAY 98 | DWG NAME: QTRS-FF_1