

N62604.AR.000761  
NCBC GULFPORT  
5090.3a

PRESENTATION SLIDES FROM RESTORATION ADVISORY MEETING REGARDING  
AGREED ORDER AND INSTALLATION RESTORATION PROGRAM UPDATE NCBC  
GULFPORT MS  
5/1/2009  
NCBC GULFPORT

# Agreed Order and Installation Restoration Program Update


May 2009

Robert Fisher  
RAB Co-Chair

**RAB**



*Gulfport, Mississippi*



SITE 7

SITE 2

SITE 3

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10

**Legend**

 Approximate


 Installation



# Site 1 – Disaster Recovery Disposal Area Landfill

- Site 1 is an inactive landfill where a mock disaster recovery training area was located.
- The landfill was used from 1942-1948.
- The Remedial Investigation is nearing completion and report is underway.
- A Feasibility Study is underway and funding is available for the Proposed Plan, Decision Document and Remedial Design.





SITE 7

SITE 2

SITE 3

SITE 8A

SITE 8B

SITE 8C

SITE 1

SITE 4

SITE 6

SITE 5

SITE 10

**Legend**

Approximate

Installation

0 1,500 Feet


# Site 2 – World War II Landfill

- Site 2 is an inactive landfill where general refuse generated at the base was disposed.
- The landfill was used from 1942-1948.
- A Remedial Investigation is now funded and will begin in 2009.

**RAB**



Gulfport, Mississippi



SITE 3

SITE 2

SITE 7

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10




**Legend**

-  Approximate
-  Installation

# Site 3 – The Northwest Landfill and Burn Pit

- Site 3 is an inactive landfill that was the primary disposal area from 1948-1968.
- A burn pit on site was used for fire-fighting training from the mid-1950's to 1966.
- The Remedial Investigation fieldwork is completed and a report is in review.
- A Feasibility Study is underway and the Proposed Plan, Decision Document and Remedial Design are funded.





SITE 3

SITE 2

SITE 7

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10

0

1,500

Feet

### Legend



Approximate




Installation

# Site 4 – Golf Course Landfill

- Site 4 operated as a landfill from 1966-1972.
- A Remedial Investigation and Feasibility Study have been completed and the reports are in review.
- Proposed Plan, Decision Document and Remedial Design are underway but waiting for RI/FS approval and planned for FY09.





SITE 7

SITE 2

SITE 3

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10

**Legend**

 Approximate


 Installation



# Site 5 – Equipment Training Area Landfill

- The landfill located at Site 5 operated from 1972-1976.
- A Remedial Investigation and Feasibility Study are complete and have final approval.
- The Proposed Plan, Public Comment Period, Decision Document and Remedial Design are complete.
- The remediation work is scheduled to be finished in June 2009.





SITE 3

SITE 2

SITE 7

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10

0

1,500

Feet

### Legend




Approximate



Installation

# Site 6 – Fire Fighting Training Area

- Site 6 contained two fire-fighting training pits which operated between 1966 and 1975.
- Long-term monitoring to evaluate the progress of natural attenuation at the site has begun.
- One year of monitoring is complete.
- Additional monitoring will be conducted.



SITE 3

SITE 2

SITE 7

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10




**Legend**

-  Approximate
-  Installation

# Site 7 – Rubble Disposal Area

- This 3-acre site reportedly received only construction rubble from 1978-1984.
- A Remedial Investigation is now planned for 2011.





SITE 7

SITE 2

SITE 3

SITE 4

SITE 1

SITE 8A SITE 8B SITE 8C

SITE 6

SITE 5

SITE 10



**Legend**

-  Approximate
-  Installation


# Site 8 - The Former Herbicide Orange Storage Area

- Canal Road excavation is complete. Additional cover (wear surface) as necessary.
- Other areas along the Canal/Turkey Creek are under investigation and a third sampling event is planned for this week.

**RAB**



Gulfport, Mississippi



SITE 3

SITE 2

SITE 7

SITE 4

SITE 1

SITE 8A

SITE 8B

SITE 8C

SITE 6

SITE 5

SITE 10



**Legend**

-  Approximate
-  Installation

# Site 10 – Parade Ground Ditch

- PCBs were found in the ditches of the NCBC Gulfport parade ground.
- Remedial actions were taken in 1999 to remove the source of PCB contamination.
- The Remedial Investigation/Feasibility Study, Proposed Plan, Public Comment Period, Decision Document are complete.
- Remedial Actions are contracted but the site remedy is under review.

**RAB**



Gulfport, Mississippi