

N00207.AR.002286
NAS JACKSONVILLE
5090.3a

LETTER REGARDING REGULATORY REVIEW AND ACCEPTANCE OF FINAL SITE
INVESTIGATION REPORT FOR POTENTIAL SOURCE OF CONTAMINATION 45 BUILDING
200 WASH RACK NAS JACKSONVILLE FL
8/31/2011
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Florida Department of Environmental Protection

Bob Martinez Center
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Rick Scott
Governor

Jennifer Carroll
Lt. Governor

Herschel T. Vinyard Jr.
Secretary

August 31, 2011

Ms. Adrienne Wilson
Code OPDE3/AW
Department of the Navy
Naval Facilities Southeast
Attn: Ajax Street, Building 135N
P.O. Box 30A
Jacksonville, FL 32212-0030


RE: Final Site Investigation Report for Potential Source of Contamination 45,
Building 200 Wash Rack, Naval Air Station Jacksonville, Jacksonville, Florida

Dear Adrienne:

I have completed my review of the Final Site Investigation (SI) Report for Potential Source of Contamination 45, Building 200 Wash Rack, Naval Air Station Jacksonville, dated July 2011 (received July 19, 2011), prepared and submitted by Tetra Tech NUS, Inc. My comments on the Draft SI Report have been adequately resolved and incorporated into the Final SI Report. Therefore, the report is accepted and approved as final. Per the recommendations in the report, a Remedial Investigation should be initiated. The investigation should attempt to identify the source of the groundwater contamination that was identified in the SI and delineate the nature and extent of the contamination in both vertical and horizontal directions.

If you have any concerns regarding this letter, please contact me at (850) 245-8997.

Sincerely,


David P. Grabka, P.G.
Remedial Project Manager
Federal Programs Section
Bureau of Waste Cleanup


31 August 2011
date

Mrs. Adrienne Wilson

August 31, 2011

Page 2 of 2

CC: Pete Dao, EPA Region IV, Atlanta
Tim Curtin, NASJAX
Mark Peterson, TtNUS, Jacksonville
Casey Hudson, CH2M Hill, Atlanta

JJC  ESN ESN