N00207.AR.002570
NAS JACKSONVILLE
5090.3a

PHOTOGRAPHIC LOG REGARDING POTENTIAL SOURCE OF CONTAMINATION 1 (PSC1)

RDS NAS JACKSONVILLE FL

7/1/1992

NAS JACKSONVILLE

TITLE: PSC 1 RDS

DATE(S): 7/1/1992, 4/21/1994

NW side of
OU 2

photo D 7/2/92

Drainage swale discharges onto Navy property and forms the little drainage/creek at the west end of PSC 1

NAS JAX RDS

4/21/94

PSC 1 : Looking SW

NAS JAX RDS

4/4/94

PSC 1 : Rubble, looking S.

NAS JAX RDS

4/21/94

PSC 1: Rusty sediment near outfall. Looking S.

Photo B
7/2/92
NW boundary of OU2
brief case (1.5') for
~~scale~~ scale
you can see the road
in the background
through the fence

photo C
7/2/92
NW boundary of OU-2
shot of concrete drainage swale on west side of site fence - swale passes under road (via culvert) the which leads to the gate

NAS JAX RDS
4/21/94

PSC 1 - NW end of site looking NW

photo A
7/2/92
NW boundary of OU 2
showing distance from
fence to ground

PSL 1

PSC 1

PSC 1

PSC 1

PSC1

PSC1

PSC 1

PSC1

PSC 1

NAS JAX

7/10/92


1

PSC1

PSC 1
NAS JAX
7/1/92

PSC 1

PSC 1
NAS JAX
7/1/92