N00207.AR.002582
NAS JACKSONVILLE
5090.3a

PHOTOGRAPHIC LOG REGARDING POTENTIAL SOURCE OF CONTAMINATION 44 (PSC44) RDS OF DRAINAGE DITCHES SOUTH OF SARATOGA STREET FROM MANATEE POINT WEST TO OUTFALL AND CULVERTS SOUTH OF BIRMINGHAM AVENUE NAS JACKSONVILLE FL
4/21/1994
NAS JACKSONVILLE

TITLE: PSC 44 RDS OF DRAINAGE DITCHES: SOUTH OF SARATOGA STREET, FROM MANATEE POINT WEST TO OUTFALL, AND CULVERTS SOUTH OF BIRMINGHAM AVENUE

DATE(S): 4/21/1994-4/22/1994

NAS JAX RDS

4/21/94

PSC 44: Drainage ditch looking N to Yorktown St. and Hangar 1000

NAS JAX RDS

4/22/94

PSC 44: From Manatee Point looking W towards outfall of ditch.

NAS JAX RDS

4/21/94

PSC 44: Facing N into Yorktown St. culvert.
Note rusty color.

NAS JAX RDS

4/21/94

PSC 44: S of Yorktown St. along ditch. Note rusty sediments, vegetation.

NAS JAX RDS

4/22/94

PSC 44: Culvert S of Birmingham Ave.

NAS JAX RDS

4/21/94

PSC 44: Ditch looking S from Saratoga St.
Note sheen on water.