

N42237.AR.000009
NSB KINGS BAY
5090.3a

LETTER REGARDING GEORGIA DEPARTMENT OF NATURAL RESOURCES APPROVAL
OF THE CURRENT SANITARY LANDFILL AT NSB KINGS BAY GA
6/5/1981
GEORGIA DEPARTMENT OF NATURAL RESOURCES



Department of Natural Resources

RECEIVED

ENVIRONMENTAL PROTECTION DIVISION
270 WASHINGTON STREET, S.W.
ATLANTA, GEORGIA 30334

JOE D. TANNER
Commissioner

JUN 19 1981

J. LEONARD LEDBETTER **MUNICIPAL SOLID WASTE**
Division Director

Reply To: *fu*
1200 Glynn Avenue
Brunswick, Georgia 31523
(912) 264-7284

5 June 1981

The Honorable Harry Callahan
Chairman, County Commissioners
Camden County Courthouse
Woodbine, GA 31569

RE: Inspection of Solid Waste Disposal Site at Kings Bay
Camden County

Dear Mr. Callahan:

On 4 June 1981, I inspected the waste disposal site at Kings Bay in Camden County to determine compliance with the Solid Waste Handling Permit, No. 020-001D(SL) issued to the Camden County Commissioners on 10 March 1976 and the Georgia Rules and Regulations for Solid Waste Management. Mr. Bill Townsend, assistant landfill operator, accompanied me on the inspection.

The sanitary landfill received a rating of 100 and is an acceptable sanitary landfill.

Enclosed is a copy of the inspection report. If I can be of assistance, please contact me.

Sincerely,

C. J. Knowlton
C. Jerry Knowlton
Environmental Specialist

CJK:rlt

cc: McCall ✓
Brandt

			Rating
<input checked="" type="checkbox"/> A*	<input type="checkbox"/> U*	7. Grading (0,4) a. maintenance of existing eroded areas b. slope of surface of disposal area sufficient to maximize runoff and minimize erosion	4
<input checked="" type="checkbox"/>	<input type="checkbox"/>	8. Drainage (0, 4) a. adequate system of diversion ditches to minimize runoff onto the surface of the disposal area and/or drainage ditches to lower the water table b. adequate drainage provisions from the surface of the disposal area c. maintenance of drainage structures and ditches	4
<input checked="" type="checkbox"/>	<input type="checkbox"/>	9. Continuity (0, 2) a. all-weather access roads b. provisions for prompt equipment repair or replacement, when needed	2
<input checked="" type="checkbox"/>	<input type="checkbox"/>	10. Environmental Protection a. Air (0, 2) 1) dust control 2) odor control b. Land (0, 2) 1) exposed rubbish and debris (except in designated reclamation areas) 2) finished areas grassed or otherwise protected to prevent erosion c. Water (0, 5) 1) leachate control (if samples taken, check here <input type="checkbox"/> . Laboratory analyses should be attached to report.) 2) potential floating debris found in or near drainage facilities 3) placement of refuse above water table 4) disposal area adequate distance from river, stream, or impoundment (normally 50 feet)	2
<input checked="" type="checkbox"/>	<input type="checkbox"/>		2
<input checked="" type="checkbox"/>	<input type="checkbox"/>		5
<input checked="" type="checkbox"/>	<input type="checkbox"/>		4
<input checked="" type="checkbox"/>	<input type="checkbox"/>	11. Supervision (0, 4) a. site under supervision of responsible individual b. responsible individual at the disposal site at all times during operation	4
<input checked="" type="checkbox"/>	<input type="checkbox"/>	12. Limited Access (0, 15) a. access limited to authorized entrances b. authorized entrances closed when the site is not in operation	15
<input checked="" type="checkbox"/>	<input type="checkbox"/>	13. Litter Control (0, 4) a. litter control program (fencing or other barriers) b. entire site policed daily	4
<input checked="" type="checkbox"/>	<input type="checkbox"/>	14. Fire Protection (0, 4) a. suitable means provided to prevent fires b. suitable means provided to control fires (Stockpiled earth is considered to be the most satisfactory fire fighting material.)	4
		ADDITIONAL STIPULATIONS (0, 4) (The following items are required for this disposal operation.)	4

- A* U* 15. Informational and directional signs posted
- 16. Insect, rodent, bird, and animal control
- 17. Site communication (telephone, two-way radio)
- 18. Employee facilities (toilet and drinking water provided)
- 19. Operational records
- 20. Special provisions for immediate disposal of dead animals or highly putrescible wastes (eggs, entrails, offal, etc.)

Sanitary Landfill Rating (SLR) = 100. SLR excluding prohibited acts 100.
 SLR must be greater than 85 to be an acceptable sanitary landfill.

A* denotes acceptable parameter.

U* denotes unacceptable parameter. (A single parameter for any requirement or the additional stipulations may be sufficient to preclude any score for that requirement or the additional stipulations.)

Comments:

Drag line digging last trench according to Mr. Townsend.

- 3 cu yd front end loader, 951.
- 1 Collection truck at office.
- 1 open dump truck unloading trash.

Set to close this landfill 13 June 1981 (Saturday).
 New landfill to open 15 June 1981.

Sanitary landfill was operated in accordance with the D&O Plan.

Time of inspection: 1300-1325 Weather conditions: Partly Cloudy

Reason for inspection: Routine Other

Discussed with:

	Name	Title	Address	Telephone
1)	Bill Townsend,	Assistant Superintendent	Camden Co. Courthouse	
		of Landfill	Woodbine	31569
2)				
3)				
4)				

Copy of this report submitted to:

	Name	Title	Address	Telephone
1)	Harry Callahan,	Chairman, County	SAME AS ABOVE	
		Commissioners		
2)				
3)				

Photographs: yes no; Total number _____; Location filed _____

Inspected by: C. J. Kromer

Reviewed by: Boyer Review date: 6-9-81

Attachments: