

N61331.AR.001349
NSA PANAMA CITY
5090.3a

PHOTOGRAPHS DEPICTING SOIL SAMPLING TEST PITS AND GEOPHYSICS SWMU 2
NSWC PANAMA CITY FL
12/3/1993
CSS PANAMA CITY

**TITLE: SWMU 2
GEOPHYSICS/SOIL
SAMPLING/TEST PITS
DATE(S): 12/3/1993**



11/11/93 - SWMU 2, Geophysics



11/11/93 - SWMU 2, Geophysics



11/11/93 - SWMU 2, Geophysics



11/11/93 - ABB-ES Trailer, lead screening sample digestion



11/11/93 - ABB-ES Trailer, Atomic Absorption Unit



11/11/93 - ABB-ES Trailer, Atomic Absorption Unit



11/12/93 - SWMU 2, Cutting paths for geophysical survey



11/12/93 - SWMU 2, Cutting paths for geophysical survey



11/13/93 - ABB-ES Trailer, lead screening analytical



11/13/93 - ABB-ES Trailer, lead screening analytical



11/13/93 - SWMU 2, Geophysics



11/15/93 - Fully packed sampling van



11/15/93 - Decontamination Pad, decontamination of surface soil sampling equipment



11/15/93 - Decontamination Pad, decontamination of surface soil sampling equipment



11/15/93 - Decontamination Pad, drying of surface soil sampling equipment



11/19/93 - ABB-ES Trailer, packing samples for shipment to analytical laboratory



11/19/93 - ABB-ES Trailer, packing samples for shipment to analytical laboratory



12/03/93 - SWMU 2, mobilizing from one Test Pit to the next



12/03/93 - SWMU 2, accessing Test Pit location



12/03/93 - SWMU 2, accessing Test Pit location



12/03/93 - SWMU 2, Test Pitting operations



12/03/93 - SWMU 2, open Test Pit with debris



12/03/93 - SWMU 2, open Test Pit with debris



12/03/93- SWMU 2, completed Test Pit



12/03/93- SWMU 2, completed and staked Test Pit



12/03/93 - SWMU 2, recording information on Test Pits