


Post-It™ brand fax transmittal memo 7671		# of pages > 1
To ANNA ULASZEWSKI	From RALPH TALMAGE	
Co. ENU.	Co. BECHTEL	
Date	Phone #	

N60258.000647  
 NSY LONG BEACH  
 SSIC # 5090.3

File #0208

CCN CTG-0037/0116

## CONTACT REPORT

Job No.: 22214-037	Date of Contact: September 7, 1994	Type of Contact:	Phone Call <input checked="" type="checkbox"/>
			Bechtel Off <input type="checkbox"/>
			Client Office <input type="checkbox"/>
			Jobsite <input type="checkbox"/>
			Other <input type="checkbox"/>
Company: Long Beach Naval Shipyard	Contact Name & Title Bill Hardin Shop 03 Public Works	Bechtel Name & Title Ralph Talmage Site Manager	
Purpose of Contact:  Bill Hardin called to inform me that Shop 03 had tested the circuit on the repaired wiring north of Building 129, on which the wrapping and shielding had been damaged during hand augering for monitoring well MW-9-05.			
Results:  Wiring checks out ok; repair has been effective. Shop 03 is satisfied and the location is released for backfill.			
Future Action to be Taken:  Talmage will refill excavation and notify ROICC and Anna Ulaszewski of closeout of this item. [Note: Hole was backfilled with sand and finished with local soil, 9/7/94]			
Prepared By: 	Location: LBNSY Trailer	Date: September 8, 1994	
Distribution:	Route	Copy	
J. Moe	—	—	Originator <input checked="" type="checkbox"/>
J. Kluesener	—	—	Others:
J. Chapman	—	—	<u>S. Livenick</u> <input checked="" type="checkbox"/>
R. Cohose	—	—	<u>A. Ulaszewski</u> <input checked="" type="checkbox"/>
M. McKee	—	—	<u>ROICC: LTCOM Barre</u> <input checked="" type="checkbox"/>
B. Kown	—	—	<u>L. Edlund</u> <input checked="" type="checkbox"/>