



DEPARTMENT OF THE NAVY  
MARE ISLAND NAVAL SHIPYARD  
VALLEJO, CALIFORNIA 94592

N00221\_000181  
MARE ISLAND  
SSIC NO. 5090.3.A

IN REPLY REFER TO:

5090  
Ser 461.6/158

MAY 16 1988

Ms. Lila Tang  
California Regional Water  
Quality Control Board  
San Francisco Bay Region  
1111 Jackson Street, Room 6040  
Oakland, Ca 94607

Dear Ms. Tang:

In accordance with paragraph C.2.d. of the Waste Discharge Requirements, (CAO # 87-170), we are providing 17 aerial photographic stereopairs showing historical development/disposal at the Facility Landfill area.

Reproduced copies of these photographs were previously forwarded to Regional Water Quality Control Board as part of the Landfill Groundwater Monitoring Program Proposal Submittal.

Sincerely,

W. J. CORNILS  
Head, Environmental-Energy  
Management Division  
By direction of the Shipyard Commander

Copy to:  
Ms. Karen Scheuerman  
U. S. Environmental Protection Agency  
Region IX  
215 Fremont Street  
San Francisco, CA 94105

Mr. John O'Kane  
North Coast California Section  
Toxic Substances Control Division  
Department of Health Services  
5850 Shellmound Drive, Suite 390  
Emeryville, CA 94608

Mr. Cliff Covey  
Solano County Health Department  
601 Texas Street  
Fairfield, CA 94533

Commander  
Western Division, Naval  
Facilities Engineering Command  
(Attention: Mr. Dean Peterson)  
P. O. Box 727  
San Bruno, CA 94066

WESTRAVAFACENCOM  
101 BUNHO  
MAY 18 1 26 PM '88

ENCLOSURES

17 AERIAL PHOTOGRAPHIC STEREOPAIRS SHOWING  
HISTORICAL DEVELOPMENT/DISPOSAL AT THE  
FACILITY LANDFILL AREA

THESE ENCLOSURES WERE NOT RECEIVED IN THE  
RESTORATION RECORD FILE.

FOR ADDITIONAL INFORMATION, CONTACT:

DIANE C. SILVA, COMMAND RECORDS MANAGER, CODE EV33  
NAVAL FACILITIES ENGINEERING COMMAND, SOUTHWEST  
1220 PACIFIC HIGHWAY (NBSD BLDG. 3519)  
SAN DIEGO, CA 92132

TELEPHONE: (619) 556-1280  
E-MAIL: [diane.silva@navy.mil](mailto:diane.silva@navy.mil)