

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

SAN FRANCISCO BAY REGION

1111 JACKSON STREET, ROOM 6040
OAKLAND 94607

Phone: Area Code 415
464-1255



June 20, 1989
File No. 2224.8009 (LWT)

Mr. Michael Cain
Environmental Division, Code 189
Building 566
Naval Air Station Moffett Field
Moffett Field, CA 94035-5000

Subject: Transmittal of compliance Inspection Report for Naval Air Station
Moffett Field, Santa Clara County

Dear Mr. Cain:

Please find enclosed a copy of a Compliance Inspection Report relative to
observations made on March 20, 1989 as a part of this Regional Water Quality
Control Board's continuing compliance checking program.

The report notes violation of the Cease and Desist Order No. 87-125 compliance
time schedules. Because of the ongoing Interagency Agreement negotiations, no
reply is necessary.

If you have any questions, please call Lila Tang at (415)464-0884.

Sincerely,

Steve Morse
Division Chief
South Bay Toxics Cleanup

Enclosure

cc: ~~Kathy Nakazawa~~ Wes Div NFEC
Lewis Mitani, EPA
Don Cox, DHS

681

RWGCB/NAVY 33

WDS INSPECTION FORM

Facility ID # 2 438009001

Agency Name Moffett Field Naval Air Station

Inspection Date 3/20/89

Facility Name _____

Was (will) this INSPECTION (be) reported to EPA (Y/N)? N

SELECTION OF INSPECTION TYPE CODE

Any violations noted (Y/N)? ~~N~~ Y*

- 1 - "A" Type Compliance Inspection
- 2 - "B" Type Compliance Inspection
- 3 - Follow-up Inspection (noncompliance)
- 4 - Follow-up Inspection (enforcement)
- 5 - Complaint Inspection
- 6 - Pre-requirement Inspection
- 7 - Miscellaneous Inspection

Inspector's Initials LWT

File # 2224 8009

WHAT TYPE OF INSPECTION WAS MADE? (1-7) 2

Short Inspection Comment (100 characters) Drove around sites with Michael Cain & Jim Meyer.
Violation of Compliance time schedule of CDC.

Additional Comments The following observations were made:

Site 12 - Diked area contained ~ 1 ft water, brownish green in color. No oil sheen noted.

Site 8 - IT personnel was purging well R-1A prior to sample collection

Site 1 - cover had dense vegetation, no ponding but uneven surface. Leslie ponds downgradient had green rings at waters edge, probably algae.

Site 2 - some ponding on roads, currently used for storing inert soils and other materials.

Site 3 - there was water flowing in the ditch, no oil sheen on water.

* If results show a violation, You must submit a Violation Input Form