

Activity file

DEPARTMENT OF THE NAVY
 NAVAL TRAINING CENTER
 SAN DIEGO, CALIFORNIA 92133-5000

AR_N00247_000156

NTC SAN DIEGO

SSIC NO. 5090.3.A

IN REPLY REFER TO:

5090

010/ **1545**

24 DEC 1991

Ms. Mary Peters
 County of San Diego
 Department of Health Services
 Hazardous Materials Management Division
 P. O. Box 85261
 San Diego, CA 92186-6261

Dear Ms. Peters:

The purpose of this letter is to provide a status for unauthorized release #T1717/H80010. This case exists because of a failed precision tank test for the unleaded gasoline tank (#344-2) at the Navy Exchange Gas Station located at the Naval Training Center.

As reported in our letter of August 19, 1991, the failed tank test is believed to be caused by a faulty vapor recovery system. Our plan of action is to replace the vapor recovery system and retest the unleaded gas tank system.

For questions, please contact Ms. Martha Gandy, Environmental Engineer, at 524-1022.

Sincerely,

J. C. VESELENAK
 Lieutenant Commander, U. S. Navy
 Staff Civil Engineer
 By direction of
 the Commander

Copy to:

Navy Resale Activity

→ SW EFD (Code 18)