



DEPARTMENT OF THE NAVY  
NAVAL TRAINING CENTER  
SAN DIEGO, CALIFORNIA 92133

AR\_N00247\_000159  
NTC SAN DIEGO  
SSIC NO. 5090.3,A

IN RE: TO:

5090  
010/

0941

08 MAY 1992

Copy *MM*

184

file NTC

Ms. Vickie Church  
County of San Diego  
Environmental Health Services  
P. O. Box 85261  
San Diego, CA 92138-5261

Dear Ms. Church:

The purpose of this letter is to provide a status for Unauthorized Release #T1717/H80010. This case exists because of a failed precision tank test for the unleaded gasoline tank (#344-2) at the Navy Exchange Gas Station located at the Naval Training Center.

As stated in previous reports, the failed tank test is believed to be caused by a faulty vapor recovery system. We plan to replace the vapor recovery system as soon as funding is arranged. Difficulty in obtaining funds for the project has delayed replacement of the system. As soon as the funding problem is resolved, we will advise you of our replacement schedule.

For question, please contact Ms. Martha Gandy, Environmental Engineer, at 524-1022.

Sincerely,

J. C. VESELENAK  
Lieutenant Commander, U. S. Navy  
Staff Civil Engineer  
By direction of  
the Commander

Copy to:  
Navy Resale Activity  
EFD SW (Code 18)